



Dolphin MXH95x Transparent Adapter Firmware Release Note

November 30th, 2022

Version 2.7

Table of Contents

1	Introduction	3
1.1	Supported topologies.....	3
1.2	BMC Firmware versions	3
1.3	PFX FLASH Versions.....	4
1.4	Known issues and planned improvements	4
2	Appendix.....	5
2.1	How to determine the Firmware versions	5
2.1.1	Linux platforms	5
2.1.2	Windows platforms.....	5
2.1.3	Example output.....	5
2.2	How to upgrade the firmware.....	5
2.2.1	Linux platforms	5
2.2.2	Windows platforms.....	5
2.3	How to contact Dolphin Support	6

DISCLAIMER

DOLPHIN INTERCONNECT SOLUTIONS RESERVES THE RIGHT TO MAKE CHANGES WITHOUT FURTHER NOTICE TO ANY OF ITS PRODUCTS TO IMPROVE RELIABILITY, FUNCTION, OR DESIGN. DOLPHIN INTERCONNECT SOLUTIONS DOES NOT ASSUME ANY LIABILITY ARISING OUT OF THE APPLICATION OR USE OF ANY PRODUCT.

LIFE SUPPORT POLICY

DOLPHIN INTERCONNECT SOLUTIONS' PRODUCTS ARE NOT AUTHORIZED FOR USE AS CRITICAL COMPONENTS IN LIFE SUPPORT DEVICES.

1 Introduction

This release note covers the MXH95x PCIe Gen4 x16 Transparent Adapter card firmware. The firmware consists of Microchip PFX runtime executables and configuration data and Board Management Controller firmware (BMC config). This release note contains a summary of the changes made. Please contact Dolphin for details.

1.1 Supported topologies

The latest firmware supports the following transparent configurations. The actual maximum link width and number of links are limited by the type of card / number and type of FireFly modules mounted. More information can be found in the MXH95x Transparent Adapter Users Guide.

- Single Transparent x16 Host
- Dual Transparent x8 Host
- Quad Transparent x4 Host
- Transparent Target single upstream link x4-x16 – single x16 downstream Edge
- Transparent Target single upstream link x4-x16 – dual x8 downstream Edge
- Transparent Target single upstream link 4x-x16 – quad x4 downstream Edge

1.2 BMC Firmware versions

The Firmware version covers the MXH95x BMC firmware changelog

Firmware version	Release date	Note
1.0	September 24 th 2020	Initial firmware release. Support for single x16 link.
1.1	November 12 th , 2020	<ul style="list-style-type: none">• Added reset LED, 500ms pulse triggered by EDGE_PERST falling edge.• Create 5ms reset pulse on all cables in a logical port.
1.2	December 3 rd , 2020	<ul style="list-style-type: none">• Adds Board Firmware Recovery support.• Adds support for transparent dual x8 and quad x4 configurations.
1.4	February 25 th 2021	<ul style="list-style-type: none">• Adds firmware version reporting.• FireFly temperature and voltage readouts.
1.5	March 12 th , 2021	<ul style="list-style-type: none">• Fixed issue with reset on dual x8 configurations Bundled with eXpressWare 5.18
2.0	June 24 th 2021	<ul style="list-style-type: none">• Added longer delay before releasing PFX from reset after power on in order to allow clocks to stabilize.• Fixed link status issues with MR2 PFX firmware.
2.1	October 29 th 2021	<ul style="list-style-type: none">• Added support for MXH95x C revision cards.• Added support for overtemperature shutdown and DIP-switch to disable. Bundled with eXpressWare 5.19.2
2.5	February 3 rd 2022	<ul style="list-style-type: none">• Companion releases PFX FLASH version 4 - MR4 checksum.
2.6	February 24 th 2022	<ul style="list-style-type: none">• Disables green blinking of Link status LED for Gen3 Link speed (MXH95x only).
2.7	April 24 th 2022	<ul style="list-style-type: none">• Adds support for 3 and 5 slot backplanes.• Added support for extended serial number format
2.8	May 16 th 2022	<ul style="list-style-type: none">• Add support for FireFly G3 firmware 16.16• Improved cable present detect for reduced systems (where some cables are missing / malfunctioning vs the configured width) Bundled with eXpressWare 5.20.0
2.9	October 7 th 2022	<ul style="list-style-type: none">• Added support for MXH94x/95x Rev CD with PM40052 chip Bundled with eXpressWare 5.20.2 and newer

1.3 PFX FLASH Versions

The PFX FLASH version changelog. Please note that the Dolphin software tools report the PFX FLASH version as the EEPROM version.

PFX Multiconfig version	Release date	Note
1	October 13th, 2020	Initial internal firmware release. <ul style="list-style-type: none">• Support for single link configurations.• PMC Firmware version pm74605_pfx_03600049
2	December 10th, 2020	<ul style="list-style-type: none">• Updated GPIO control required by BMC version 1.2• Fixes PFX upgrade problem
3	February 16th, 2021	<ul style="list-style-type: none">• Applied PFX: MR2 3.70.0.4F Bundled with eXpressWare 5.18
4	July 6 th 2021	<ul style="list-style-type: none">• ChipLink version 1.62.00• Fixed PCI-SIG compliance test issues. STATUS PASS• Enabled CTS on UPS• Enabled AER reporting on CTS• Set Link Capability (LnkCap) 0x70 for USP (vEP)• Enabled Reset Partition on USP link down• Increased TLP throttling from 50.000 to 70.000 (Microchip recommendation)• Added support for MXH95x C revision cards. Bundled with eXpressWare 5.19.2
5	February 24 th 2022	Applied Microchip MR4 3.90.0.5b <ul style="list-style-type: none">• File format 3.90.0.5b• ChipLink version 1.68.00• Fixes MR2 related problem with Optical support that could cause link to train to lower speed or narrower links.
6	May 16th 2022	<ul style="list-style-type: none">• Added GPIO control for improved cable present detect. Bundled with eXpressWare 5.20.0 and newer

1.4 Known issues and planned improvements

- PFX Synthetic Endpoint is planned for MXH950.

2 Appendix

2.1 How to determine the Firmware versions

The version of the firmware components can be retrieved using the **dis_diag** tool. Please see options using **-h** option. This tool is available by installing eXpressWare Board Management Software 5.18 or newer. The software is available for both Windows and Linux and can be downloaded from www.dolphinics.com/mx

2.1.1 Linux platforms

```
# cd /opt/DIS/sbin
# ./dis_diag
```

2.1.2 Windows platforms

```
> cd %ProgramFiles%\Dolphin Express MX\Util
> .\dis_diag
```

2.1.3 Example output

```
# dis_diag
=====
Dolphin diagnostic tool -- dis_diag version 5.18.0 (Mon Oct 12 16:44:17 CET 2020)
=====

dis_diag compiled in 64 bit mode
Driver : Dolphin IRM (GX) 5.18.0 Oct 24th 2020 (rev 33fff3a)
Date   : Mon Oct 12 12:59:28 CET 2020
System : Linux somenode 3.10.0-514.21.1.el7.x86_64 #1 SMP Thu Oct 12 17:04:51 UTC 2020
x86_64 x86_64 x86_64 GNU/Linux

Number of configured local adapters found: 1

Adapter 0 > Type           : MXH952
           Mode           : TRANSPARENT
           NodeId         : 4
           Serial number   : MXH952-CC-000015
           MXH chip family : MICROSEMI - PFX GEN4
           MXH chip vendorId : 0x11f8
           MXH chip device  : 0x4036
           MXH chip revision : 0x0 (ZB)
           EEPROM version   : 5
           EEPROM vendor info : 0x0000
           Firmware version : 2.6
           Card revision    : CC
```

2.2 How to upgrade the firmware

The firmware can be upgraded using the **upgrade_eeprom** utility bundled with eXpressWare version 5.18 or newer.

2.2.1 Linux platforms

```
# cd /opt/DIS/sbin
# ./upgrade_eeprom.sh --upgrade
```

2.2.2 Windows platforms

Start PowerShell with administrative capabilities (Press Windows+X, select Windows PowerShell (Admin))

```
PS > cd "${env:ProgramFiles}\Dolphin Express MX\Util"
PS > Set-ExecutionPolicy AllSigned -Scope Process
PS > .\upgrade_eeprom.ps1 --upgrade
```

Please carefully review the output from the upgrade utility.

A complete power cycle of the system (including removal of AuxPower) is required after the firmware upgrade.

Please verify the firmware upgrade was successful after system is powered on again following the steps found in section 2.1 How to determine the Firmware version above.

2.3 How to contact Dolphin Support

Please contact Dolphin support at pci-support@dolphinics.com if you have any questions or issue.